

Cope

Attorney Docket No. 1466.1052

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Seiichi IWASA, et al.

Application No.: 10/028,367

Confirmation No.: 3361

Filed: December 28, 2001

U.S. Patent No.: 6,937,213 B2

Issued: August 30, 2005

For: METHOD AND DEVICE FOR DRIVING PLASMA DISPLAY PANEL



ATTENTION

CERTIFICATE OF CORRECTION

BRANCH

Certificate
MAR 20 2006
of Correction

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: March 14, 2006

By: [Signature]
H. J. Staas
Registration No. 20,010

1201 New York Ave, N.W., 7th Floor
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

MAR 21 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 6,937,213 *B2*

DATED : August 30, 2005

INVENTOR(S) : Seiichi IWASA, et al.

Column 22, line 34, after "voltage" insert -- to --

Column 24, line 31, change "sources" to -- source --

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP
1201 New York Ave., N.W.
7th Floor
Washington, DC 20005

PATENT NO. 6,937,213

No. of add'l copies
@ 50¢ per page

⇒

MAR 21 2006